# Non-Sterile Cleanroom Gowning Procedure

#### STEP 1: PRE-ENTRY



**Bouffant/Hair Net** Be sure to contain all hair.



В

**Shoe Covers** Contain all laces and tassels.



**STEP 2: GOWNING** 




**Gowning Gloves** Recommended for Class 100 and better.





Mask Worn over or under hood. Bend nosepiece first for a snug facial fit.





Hood Ensure snug fit and proper face/neck seal.



STEP 3

#### Coverall

Step into the coverall. Be sure sleeves and upper garment do not touch bench or floor.

Tuck shoulder panels from hood inside coverall before zipping up.



#### STEP 4

### **Boot Covers**

Put on boots and pull boots (high-top shoe covers) over legs of coverall.

If cross-over bench is used, transfer each foot to cleaner side of bench as boot is donned.



### STEP 5

#### **Goggles** Wear goggles/safety glasses when eye protection or additional particulate

control is desired.



## STEP 6

#### **Cleanroom Gloves (optional)**

Place hem of glove over cuff of sleeve. Put on over gowning gloves or remove gowning gloves and then put on cleanroom gloves.



# Non-Sterile Cleanroom Gowning Removal Procedure

## **STEP 1: IN ORDER**



# **Gloves**

If two pairs of gloves are worn, remove top pair of gloves, then discard.









**Goggles/Safety Glasses** Remove and properly

contain.





**Boot Covers** Usually discard after each change.



## STEP 2



Coverall If coverall is to be used again, either hang it in a controlled environment or prepare for storage.



**Hood** Hang in controlled environment.




discard.

C






## STEP 3



Gloves It is recommended that gloves be discarded after each change.



**Bouffant/Hair Net** Usually discard after each change.



**Shoe Covers** Usually discard after each change.